

United States Environmental Protection Agency Washington, D.C. 20460

| | | | <i>Nater Compliance Ins</i> | | | | | |
|--|---|------------------------|--|---|---------------------------|-----------------|------------------------|--|
| | ·········· | | SECTION A: National Data | Syst | em Coding (i.e., PCS) | I | - Engility Tyma | |
| | Transaction Code N 5 TN | NPDES 0068659 | | I | nspection Type C | Inspecto S | or Facility Type 1 | |
| | | | Rema | rks | | | | |
| | | | | | | | | |
| Inspection Work Days Facility Self-Mo | | | -Monitoring Evaluation Rating | | BI QA N N | | Reserved | |
| | 1.0 | ···· | | | | | | |
| | 1 T (* CT:*12. | T | SECTION B: 1 | | lity Data Entry Time/Date | | Permit Effective Date | |
| | me and Location of Facility TW, also include POTW name and | | d (For industrial users discharging to ermit number) | | 11/06/15 1:30 PM | 1 20111/ 1 2011 | | |
| Big Springs Water Treatment Plant | | | | | Exit Time/Date | | Permit Expiration Date | |
| 213 Water Plant Road, Elizabethton, TN 37643 | | | | | 11/06/15 3:30 PM | | 15/6/30 | |
| Names of On-site Representative(s)/Title(s)/Phone and Fax Number(s) Teresa Nidiffer/Water Department Director/(423) 547-6207 Doug Cornett/Water Plant Manager/(423) 547-6450 Jim Roberts/District Supervisor Name, Address of Responsible Official/Title/Phone and Fax Number Teresa Nidiffer, 136 Sycamore St., Elizabethton, TN Contacted Yes \[\sum \] No | | | | | | | CS, and other | |
| | | | | | | | | |
| SECTION C: Areas Evaluated During Inspection (Check only those areas evaluated) V Parmit Y Self-Monitoring Program Prefreatment MS4 | | | | | | | | |
| X | Permit | X | Self-Monitoring Program | | Pretreatment | | 19154 | |
| X | Records/Reports | X | Compliance Schedules | X | Pollution Prevention | | | |
| X | Facility Site Review | X | Laboratory | | Storm Water | | | |
| X | Effluent/Receiving Waters | X | Operations & Maintenance Combined Sewer Overflow | | | | | |
| X | Flow Measurement | X | Sludge Handling/Disposal | dge Handling/Disposal Sanitary Sewer Overflow | | | | |
| | | | SECTION D: Summary o | f Fi | ndings/Comments | ion anden | no se apaconero) | |
| | (Attach addition) | al sheets | of narrative and checklists, in | <u>clud</u> | ing Single Event Violati | ion coaes, | as necessary) | |
| | | | See Attached | Repo | ort | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Name(s) and Signature(s) of Inspector(s) Agency/Office/Phone and Fav | | | | | x Numbers | | Date | |
| Brov | wn Patton | tte | TDEC/DWPC/JCEFO/(4 | OWPC/JCEFO/(423)854-5458 Fax (423)854-5401 | | | 7-26-11 | |
| | | | | | | | | |
| | | | | , | | | | |
| Sign | ature of Management QA R | Agency/Office/Phone an | x Numbers | | Date | | | |
| L | frees & Horto | n | TDEC/DWPC/JCEFO/(4 | TDEC/DWPC/JCEFO/(423)854-5447 Fax (423)854-5401 | | | 7-26-11 | |

TDEC/DWPC/JCEFO/(423)854-5447 Fax (423)854-5401
EPA Form 3560-3 (Rev 1-06) Previous Editions are obsolete.



Johnson City Field Office TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION 2305 SILVERDALE ROAD JOHNSON CITY, TENNESSEE 37601-2162 (423) 854-5400 STATEWIDE 1-888-891-8332 FAX (423) 854-5401

July 21, 2011

Teresa Nidiffer Big Springs Water Treatment Plant 136 South Sycamore Street Elizabethton, TN 37643 Certified Mail # 70103090000087549201 Return Receipt Requested

Re: Notice of Violation

Big Springs Water Treatment Plant NPDES Permit No. TN0068659 Carter County

Dear Ms. Teresa Nidiffer:

On June 15, 2011, personnel from this office conducted a Compliance Evaluation Inspection (CEI) of the Big Springs Water Treatment Plant. The purpose of the CEI was to evaluate compliance with the General NPDES Permit for Discharges of Filter Backwash and Sedimentation Basin Wastewater from Water Treatment Plants. The following violation was observed during this CEI:

- 1. Discharge Monitoring Reports (DMR), submitted to this office spanning the previous three years were reviewed during site inspection. The review indicated that there were no violations of the permit parameters. Personnel from Big Springs WTP informed personnel from this Division that samples are taken from within the sedimentation basin utilizing a dipping technique. Section 7.1of the General NPDES Permit for Discharges of Filter Backwash and Sedimentation Basin Washout From Water Treatment Plants states that samples and measurements shall be taken after treatment of the filter backwash and sedimentation basin wash water and prior to mixing with contaminated or uncontaminated storm water runoff or the receiving stream. Samples must be taken at discharge pipe after sedimentation basin.
- 2. Water Treatment Plants covered under this permit must also include Flow Rate on the DMR. Big Springs WTP uses an in-line flow meter which measures the flow rate being released after the filter backwash process. The Actiflo System is also generating waste water being discharged into the sedimentation basin, which is included in the discharge

into Gap Creek but not in the flow rate reported on the DMR. The reported discharge flow rate must be representative of the <u>total</u> flow being discharged into Gap Creek.

The following comments are for your consideration:

- 1. Big Springs Water Treatment Plant is utilizing the pre-treatment process Actiflo which uses microsand as seed for floc formation. This process causes recurring bypasses into the settling basin of raw water. Wastewater is produced from filter backwashing from which the wastewater is pumped to a concrete settling basin. There is a continuous flow discharge, alternating from the two settling basins into Thomas Creek at mile 0.4 to the South Fork Holston River, which is the only outfall covered under the current permit. The overall maintenance and operation of the facility appear to be in good standing.
- 2. All analyses are performed on-site by Big Springs Water Treatment Plant personnel. Records and maintenance as well as sampling and analysis procedures were reviewed during inspection and satisfy permit requirements. All laboratory equipment is calibrated semi-annually by Labtronix as well as daily calibrations performed by Big Springs Water Treatment Plant personnel. All records are retained on-site on all equipment calibrations.
- 3. The sedimentation basin has been cleaned out once in the past three years on October 20, 2010. The clean-out, handling and disposal was contracted out to Appalachian Environmental Inc.
- 4. The outfall to Gap Creek was visited during the inspection. There was no visible adverse effect of the discharge on the receiving stream. The outfall has been posted with a sign satisfying the permit requirements.

I would like to thank Ms. Teresa Nidiffer, Mr. Doug Cornett, Ms. Lisa Childers, Mr. Lawrence Jackson, and Mr. Jim Roberts for their time and cooperation during the inspection. If you have any questions you may reach me at brown.patton@state.tn.us or at (423) 854-5458.

Sincerely,

Brown Patton

Brown Patton

Division of Water Pollution Control

Johnson City Environmental Field Office

cc: Enforcement and Compliance, DWPC, 6th Floor L&C Annex, 401 Church St., Nashville, TN 37243